


**ಹುಬ್ಬಳ್ಳಿ ವಿದ್ಯುತ್ ಸರಬರಾಜು
ಕಂಪನಿ ನಿಯಮಿತ**

(ಕರ್ನಾಟಕ ಸರ್ಕಾರದ ಸಂಪೂರ್ಣ ಸ್ವಾಮ್ಯಕ್ಕೆ ಒಳಪಟ್ಟಿದೆ)
ನಿಗಮ ಕಛೇರಿ, ಪೂನಾ-ಬೆಂಗಳೂರು ರಸ್ತೆ,
ನವನಗರ, ಹುಬ್ಬಳ್ಳಿ-580025

Tel. No. 0836-2222535
Fax No. 0836-2324307



**HUBLI ELECTRICITY SUPPLY
COMPANY LIMITED**

(Wholly owned Govt. of Karnataka undertaking)

**Corporate Office, P.B. Road,
Navanagar, Hubli-580025**

Website: www.hescom.co.in

E-mail ID: seepmc@hescom.co.in
eerapdrp@hescom.co.in

Preamble:

1. This office has floated the tenders through E-Procurement portal for Repairs and reconditioning of faulty distribution transformers of capacities 25,63 and 100 kva of different makes in Dharwad Urban Division vide Tender enquiry no: HESCOM/SEEPMC/P3/RCDWD/11-12/21 Dt 26.12.2011.
2. Detailed work award was issued to M/s Pushpak Electric industries No 2/257, Pillappa Indl Estate, Hoysalanagar, Sunkadakatte, Bangalore 560058, vide D.W.A. No. HESCOM/SEEPMC/ P3 / RCDWD/ 12- 13/CYS-1092. Dt. 02.06.2012.
3. Ltr no 424/DU/AEE(O)/ TA-2/2013-14 Dt. 05.07.2013. of EE(Ele) O&M Divn HESCOM Dharwad, in which it is stated that the agency has not calibrated testing equipments and same is used for repair works and also not provided safety precautionary measure while testing.
4. Show Cause Notice was issued vide no HESCOM/SEEPMC/P3/14-15/3028-43/ Dt. 15.05.2014. of SEEPMC HESCOM as the failure of WGP transformers
5. EE(Ele) O&M(U) Divn HESCOM Dharwad. has reported that the agency has not repaired and returned 28 nos of WGP transformers vide Ltr no DWD/AEE(O)/SK/862-66 Dt. 23.05.2014.
6. EE(Ele) O&M(U) Divn HESCOM Dharwad. has reported that as on 24.05.2014. the agency has not repaired 28 nos of various capacity transformers FWGP. which are pending for a period of more than three months and hence requested for blacklisting the firm, vide Ltr no DWD/AEE(O)/TA-2/871-74 Dt. 24.05.2014.
7. EE(Ele) O&M(U) Divn HESCOM Dharwad, vide Ltr no DWD/AEE(O)/TA-2/1089-92 Dt. 05.06.2014. has reported that the percentage of failure of repaired good transformers WGP is more than 15% ,but as per DWA it should be less than 7%.
8. Chief Engineer (Ele) Hubballi Zone has stated that the firms performance is not satisfactory in O & M Division Dharwad & Karwar.
9. As per the kind approval vide para no. 92, Dtd. 27.01.2015, intimation was sent to the contractor vide Ltr. No. HESCOM/SEEPMC/P3/670/2014-15/23356-62 Dtd. 28.01.2015 to attend the personal hearing on 31.01.2015 at 11:00 Hrs. as giving him final opportunity to submit his say
10. On behalf of M/s. Pushpak Electric industries , Shri. Nagaraja Raikar, Managing Director, M/s Pushpak Electric industries, No 2/257, Pillappa Indl Estate, Hoysalanagar, Sunkadakatte, Bangalore 560091 appeared before the Competent authority of HESCOM, the Superintending Engineer(EI), Projects Monitoring Cell. Shri. Nagaraja Raikar, Managing Director submitted his arguments.

11. The following points were urged on behalf of M/s. Pushpak Electric industries , Bangalore

- a. The firm stated that the work of repairs and reconditioning of faulty distribution Transformers was awarded to it on 02.08.2012. Their One year period was completed on 03.08.2013, again extension was awarded to it for Six months. In January 2014 Executive Engineer (Ele). O & M Urban Division HESCOM Dharwad stopped giving P.O. and Repair Center was Idle for about Six months. After that their DWA's Two years period completed on 03.08.2014, and consequently HESCOM Shed was vacated. The firm urged that Executive Engineer (Ele). O & M Urban Division HESCOM Dharwad has issued 3 nos. of P.O.'s having the total quantity of 58. nos. at a time during the month of October 2013 just before the Diwali festival. On account of Festival , all the labours have gone on leave. Because of which, repairs of such Transformers was Delayed.
 - b. The firm also urged that in Dharwad repair center, the repaired good transformers were failing frequently on account of line faults ,It could be known by seeing the nature of burnt coils. It was made known to the Executive Engineer (Ele). O & M Urban Division HESCOM Dharwad and requested him to see & verify the burnt coils. Though it was requested several times and waited for his inspection, he has not turned up and because of which, repairs and submission of such transformers was delayed.
 - c. The firm stated that the delay in procurement of raw materials was happened on account of firm's financial conditions, which has caused delay in repairs and frequent quitting /changing of labours in coastal area of Karwar also hampered its speedy functioning.
 - d. The firm requested HESCOM to consider its say and to drop the actions in black listing.
 - e. Apart from the statements submitted orally, the firm has not put-in any written statements at that instant.
12. I.O.Note approved vide para no. 124. Dated. 12.06.2015

13. Considering the above facts, and as per DWA Terms and Conditions

Hence, the Order,

No: HESCOM/SEEPROMC/EEP3/AEE1P3/670/15-16/ *CYS - 922* Date: **17 JUN 2015**

Under the circumstances explained above, M/s Pushpak Electric industries No 2/257, Pillappa Indl Estate, Hoysalanagar, Sunkadakatte, Bangalore 560058, is blacklisted from participating in any of the HESCOM works with immediate effect from the date of this order for a period of one year.


Superintending Engineer (Ele),
PMC, HESCOM, Hubli.

To

M/s Pushpak Electric industries, No
2/257, Pillappa Indl Estate, Hoysalanagar,
Sunkadakatte,
Bangalore 560091

M/s Pushpak Electric industries
No.19/20, Raghavendra Industrial Estate,
Thigalarapalya Main Road,
Bangalore - 560 058,
Telefax: 080-28367419,
Mobile : 984516965

Regd. Post with Ack. Due/E-mail

Copy submitted to PS to Addnl Chief Secretary,

Copy for kind information & needful to

1. The Chief Engineer (Ele) O & M Zone HESCOM Hubli/ Belgaum.
2. The General Manager (Tech), Corporate Office, HESCOM, Hubli.
3. The General Manager (Tech), Corporate Office, KPTCL, BESCO, , GESCOM, MESCOM, and CESC.

Copy for information & needful to

4. The Superintending Engineer (Ele) T & P Corporate Office, HESCOM, Hubli.
5. The Superintending Engineer (Ele) O & M Circle, HESCOM. Hubli/Sirsi/Haveri/
Belgaum/Chikkodi/Bijapur/Bagalakot.
6. The Controller of Account (I/A), Corporate Office, HESCOM, Hubli.
7. The Controller of Account (A/F), Corporate Office, HESCOM, Hubli.
8. The Chief Electrical Inspector, Electrical inspectorate office, (Govt of Karnataka), Crescent Road, Beside
Mallige Hospital, Bangalore.
9. Additional Chief Electrical Inspector, Electrical Inspectorate office, Sneha Building, Brindavan lay out,
Behind Sanmati Hostel, Dharwad.

Copy for information

10. The Executive Engineer (Ele), O&M Division, HESCOM., Dharwad Urban/Dharwad Rural.
11. All Executive Engineer (Ele), O&M Division, and corporate office HESCOM.
12. The Executive Engineer (Ele), MT Divn HESCOM Hubli and Belgaum.
13. Accounts Officer (I/A), O&M Division, HESCOM, Dharwad Urban/Dharwad Rural.
14. All Accounts Officer (I/A), O&M Division, HESCOM.
15. CWC to EEIT for information & to upload in HESCOM web site.

